



元智大學環科中心檢測實驗室
樣品檢驗報告

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1101C2376

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：110年07月19日14時00分

採樣地點：龜山文華館 C02/2F 飲水機

收樣時間：110年07月20日

(桃園市龜山區)

採樣單位：御安淨水企業有限公司

報告日期：110年07月22日

採樣方法：---

報告編號：C1102376-1

採樣行程代碼：---

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：	御安淨水企業有限公司	委託編號：	YZ1101C2376
委託者地址：	桃園市平鎮區中豐路南勢二段 127 號	樣品基質：	飲用水
受檢單位：	家興人力資源顧問股份有限公司	檢測目的：	定檢
行業別：	自述業別	採樣時間：	110年07月19日 14時05分
採樣地點：	龜山文華館 C09/2F 飲水機 (桃園市龜山區)	收樣時間：	110年07月20日
採樣單位：	御安淨水企業有限公司	報告日期：	110年07月22日
採樣方法：	---	報告編號：	C1102376-2
採樣行程代碼：	---		

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：	御安淨水企業有限公司	委託編號：	YZ1101C2376
委託者地址：	桃園市平鎮區中豐路南勢二段 127 號	樣品基質：	飲用水
受檢單位：	家興人力資源顧問股份有限公司	檢測目的：	定檢
行業別：	自述業別	採樣時間：	110年07月19日 14時10分
採樣地點：	龜山文華館 C10/2F 飲水機 (桃園市龜山區)	收樣時間：	110年07月20日
採樣單位：	御安淨水企業有限公司	報告日期：	110年07月22日
採樣方法：	---	報告編號：	C1102376-3
採樣行程代碼：	---		

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：	御安淨水企業有限公司	委託編號：	YZ1101C2376
委託者地址：	桃園市平鎮區中豐路南勢二段127號	樣品基質：	飲用水
受檢單位：	家興人力資源顧問股份有限公司	檢測目的：	定檢
行業別：	自述業別	採樣時間：	110年07月19日14時15分
採樣地點：	龜山文華館C11/2F飲水機 (桃園市龜山區)	收樣時間：	110年07月20日
採樣單位：	御安淨水企業有限公司	報告日期：	110年07月22日
採樣方法：	---	報告編號：	C1102376-4
採樣行程代碼：	---		

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位	: 御安淨水企業有限公司	委託編號	: YZ1101C2376
委託者地址	: 桃園市平鎮區中豐路南勢二段 127 號	樣品基質	: 飲用水
受檢單位	: 家興人力資源顧問股份有限公司	檢測目的	: 定檢
行業別	: 自述業別	採樣時間	: 110年07月19日 14時20分
採樣地點	: 龜山文華館 C12/2F 飲水機 (桃園市龜山區)	收樣時間	: 110年07月20日
採樣單位	: 御安淨水企業有限公司	報告日期	: 110年07月22日
採樣方法	: ---	報告編號	: C1102376-5
採樣行程代碼	: ---		

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：	御安淨水企業有限公司	委託編號：	YZ1101C2376
委託者地址：	桃園市平鎮區中豐路南勢二段127號	樣品基質：	飲用水
受檢單位：	家興人力資源顧問股份有限公司	檢測目的：	定檢
行業別：	自述業別	採樣時間：	110年07月19日14時25分
採樣地點：	龜山文華館C13/2F飲水機 (桃園市龜山區)	收樣時間：	110年07月20日
採樣單位：	御安淨水企業有限公司	報告日期：	110年07月22日
採樣方法：	---	報告編號：	C1102376-6
採樣行程代碼：	---		

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1101C2376

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：110年07月19日14時30分

採樣地點：龜山文華館 C14/1F 飲水機

收樣時間：110年07月20日

(桃園市龜山區)

採樣單位：御安淨水企業有限公司


報告日期：110年07月22日

採樣方法：---

報告編號：C1102376-7

採樣行程代碼：---

[illegible]



樣品檢驗報告

委託單位：	御安淨水企業有限公司	委託編號：	YZ1101C2376
委託者地址：	桃園市平鎮區中豐路南勢二段127號	樣品基質：	飲用水
受檢單位：	家興人力資源顧問股份有限公司	檢測目的：	定檢
行業別：	自述業別	採樣時間：	110年07月19日14時35分
採樣地點：	龜山文華館 C15/1F 飲水機 (桃園市龜山區)	收樣時間：	110年07月20日
採樣單位：	御安淨水企業有限公司	報告日期：	110年07月22日
採樣方法：	---	報告編號：	C1102376-8
採樣行程代碼：	---		

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C02/2F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:00

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 07/22/2021

Report Number: C1102376-1

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C09/2F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:05

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 07/22/2021

Report Number: C1102376-2

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C10/2F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:10

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 07/22/2021

Report Number: C1102376-3

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C1 1/2F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:15

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 07/22/2021

Report Number: C1102376-4

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C12/2F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:20

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Report Date: 07/22/2021

Sampling Method: ---

Report Number: C1102376-5

Sampling Code: ---

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C13/2F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:25

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 07/22/2021

Report Number: C1102376-6

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C14/1F drinking fountain

Client Number: YZ1101C2376

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 07/19/2021 14:30

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 07/22/2021

Report Number: C1102376-7

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Client Number: YZ1101C2376

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Sample Base: Drinking Water

Plant: Golden Li H.R Consultant Co., Ltd

Test purpose: Regular inspection

IndustrialType: ---

Sampling Date: 07/19/2021 14:35

Sampling Site: Lucky dorm C15/1F drinking fountain

Sample Received: 07/20/2021

Sampling Organization: Yuann International Technology Co., Ltd

Report Date: 07/22/2021

Sampling Method: ---

Report Number: C1102376-8

Sampling Code: ---

[illegible]