



行政院環保署認可證字號：041

元智大學環科中心檢測實驗室

樣品檢驗報告

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C0062

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年01月04日13時00分

採樣地點：龜山文華館 C02/2F 飲水機

收樣時間：111年01月05日

(桃園市龜山區)

採樣單位：御安淨水企業有限公司

報告日期：111年01月07日

採樣方法：---

報告編號：C1110062-1

採樣行程代碼：---

[illegible]

元智大學環科中心檢測實驗室
樣品檢驗報告

委託單位：	御安淨水企業有限公司	委託編號：	YZ1111C0062
委託者地址：	桃園市平鎮區中豐路南勢二段 127 號	樣品基質：	飲用水
受檢單位：	家興人力資源顧問股份有限公司	檢測目的：	定檢
行業別：	自述業別	採樣時間：	111 年 01 月 04 日 13 時 05 分
採樣地點：	龜山文華館 C09/2F 飲水機 (桃園市龜山區)	收樣時間：	111 年 01 月 05 日
採樣單位：	御安淨水企業有限公司	報告日期：	111 年 01 月 07 日
採樣方法：	---	報告編號：	C1110062-2
採樣行程代碼：	---		

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段127號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館C10/2F飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1111C0062
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：111年01月04日13時10分
 收樣時間：111年01月05日
 報告日期：111年01月07日
 報告編號：C1110062-3

樣品報告編號		C1110105G				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	111年01月05日 11時00分	LES Endo Agar	1 倍/0 , 0	NIEA E230.55B	6	
以下空白								

元智大學環科中心檢測實驗室
樣品檢驗報告

樣品檢驗報告

委託單位	: 御安淨水企業有限公司	委託編號	: YZ1111C0062
委託者地址	: 桃園市平鎮區中豐路南勢二段 127 號	樣品基質	: 飲用水
受檢單位	: 家興人力資源顧問股份有限公司	檢測目的	: 定檢
行業別	: 自述業別	採樣時間	: 111年01月04日 13時15分
採樣地點	: 龜山文華館 C11/2F 飲水機 (桃園市龜山區)	收樣時間	: 111年01月05日
採樣單位	: 御安淨水企業有限公司	報告日期	: 111年01月07日
採樣方法	: ---	報告編號	: C1110062-4
採樣行程代碼	: ---		

委託者地址：桃園市平鎮區中豐路南勢二段127號 樣品基質：飲用水

受檢單位：家興人力資源顧問股份有限公司 檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年01月04日13時15分

採樣地點：龜山文華館 C11/2F 飲水機

收樣時間：111年01月05日

(桃園市龜山區)

採樣單位：御安淨水企業有限公司

報告日期：111年01月07日

採樣方法：---

報告編號：C1110062-4

採樣行程代碼：---

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C0062

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年01月04日13時20分

採樣地點：龜山文華館 C12/2F 飲水機

收樣時間：111年01月05日

(桃園市龜山區)

採樣單位：御安淨水企業有限公司

報告日期：111年01月07日

採樣方法：---

報告編號：C1110062-5

採樣行程代碼： ---

[illegible]

元智大學環科中心檢測實驗室
樣品檢驗報告

樣品檢驗報告

委 託 單 位 : 御安淨水企業有限公司

委託編號：YZ1111C0062

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年01月04日13時25分

採樣地點：龜山文華館 C13/2F 飲水機

收樣時間：111年01月05日

(桃園市龜山區)

採樣單位：御安淨水企業有限公司

報告日期：111年01月07日

採樣方法：---

報告編號：C1110062-6

採樣行程代碼： ---

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段 127 號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C14/1F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1111C0062
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：111年01月04日13時30分
 收樣時間：111年01月05日
 報告日期：111年01月07日
 報告編號：C1110062-7

樣品報告編號		C1110105K				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	111年01月05日 11時00分	LES Endo Agar	1 倍/0 , 0	NIEA E230.55B	6	
以下空白								

PASS

元智大學環科中心檢測實驗室
樣品檢驗報告

委託單位	: 御安淨水企業有限公司	委託編號	: YZ1111C0062
委託者地址	: 桃園市平鎮區中豐路南勢二段 127 號	樣品基質	: 飲用水
受檢單位	: 家興人力資源顧問股份有限公司	檢測目的	: 定檢
行業別	: 自述業別	採樣時間	: 111年01月04日13時35分
採樣地點	: 龜山文華館 C15/1F 飲水機 (桃園市龜山區)	收樣時間	: 111年01月05日
採樣單位	: 御安淨水企業有限公司	報告日期	: 111年01月07日
採樣方法	: ---	報告編號	: C1110062-8
採樣行程代碼	: ---		

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C02/2F drinking fountain

Client Number: YZ1111C0062

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 01/04/2022 13:00

Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 01/07/2022

Report Number: C1110062-1

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C09/2F drinking fountain

Client Number: YZ1111C0062

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 01/04/2022 13:05

Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 01/07/2022

Report Number: C1110062-2

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C10/2F drinking fountain

Client Number: YZ1111C0062

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 01/04/2022 13:10

Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 01/07/2022

Report Number: C1110062-3

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C11/2F drinking fountain

Client Number: YZ1111C0062

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 01/04/2022 13:15

Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 01/07/2022

Report Number: C1110062-4

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden Li H.R Consultant Co., Ltd
IndustrialType: ---
Sampling Site: Lucky dorm C12/2F drinking fountain

Client Number: YZ1111C0062
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 01/04/2022 13:20
Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 01/07/2022
Report Number: C1110062-5

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden Li H.R Consultant Co., Ltd
IndustrialType: ---
Sampling Site: Lucky dorm C13/2F drinking fountain

Client Number: YZ1111C0062
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 01/04/2022 13:25
Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 01/07/2022
Report Number: C1110062-6

[illegible]

Accreditation number by EPA : 041

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd

Client Number: YZ1111C0062

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Sample Base: Drinking Water

Plant: Golden Li H.R Consultant Co., Ltd

Test purpose: Regular inspection

IndustrialType: ---

Sampling Date: 01/04/2022 13:30

Sampling Site: Lucky dorm C14/1F drinking fountain

Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd

Report Date: 01/07/2022

Sampling Method: ---

Report Number: C1110062-7

Sampling Code: ---

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden Li H.R Consultant Co., Ltd
IndustrialType: ---
Sampling Site: Lucky dorm C15/1F drinking fountain

Client Number: YZ1111C0062
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 01/04/2022 13:35
Sample Received: 01/05/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 01/07/2022
Report Number: C1110062-8

[illegible]