



元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C3793

委託者地址：桃園市平鎮區中豐路南勢二段 127 號

樣品基質：飲用水

受 檢 單 位：錄興國際股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年10月13日15時30分

採樣地點：高雄長春一館 B1/1F 飲水機

收樣時間：111年10月14日

(高雄市湖內區)

採樣單位：御安淨水企業有限公司

報告日期：111年10月20日

採樣方法：---

報告編號：C1113793-1

採樣行程代碼：---

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C3793

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：錄興國際股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年10月13日15時35分

採樣地點：高雄長春一館 B2/2F 飲水機

收樣時間：111年10月14日

(高雄市湖內區)

採 樣 單 位：御安淨水企業有限公司

報告日期：111年10月20日

採樣方法：---

報告編號：C1113793-2

採樣行程代碼： ---

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C3793

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：錄興國際股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年10月13日15時40分

採樣地點：高雄長春一館 B3/3F 飲水機

收樣時間：111年10月14日

(高雄市湖內區)

採樣單位：御安淨水企業有限公司

報告日期：111年10月20日

採樣方法：---

報告編號：C1113793-3

採樣行程代碼： ---

[illegible]



行政院環保署認可證字號：041

元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C3793

委託者地址：桃園市平鎮區中豐路南勢二段127號 樣品基質：飲用水

樣品基質：飲用水

受 檢 單 位：錄興國際股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年10月13日15時45分

採樣地點：高雄長春一館 B4/4F 飲水機

收樣時間：111年10月14日

(高雄市湖內區)

採樣單位：御安淨水企業有限公司

報告日期：111年10月20日

採樣方法：---

報告編號：C1113793-4

採樣行程代碼：---

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C3793

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：錄興國際股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年10月13日15時50分

採樣地點：高雄長春一館 B5/5F 飲水機

收樣時間：111年10月14日

(高雄市湖內區)

採樣單位：御安淨水企業有限公司

報告日期：111年10月20日

採樣方法：---

報告編號：C1113793-5

採樣行程代碼：---

[illegible]



元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1111C3793

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：錄興國際股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：111年10月13日15時55分

採樣地點：高雄長春一館 B6/6F 飲水機

收樣時間：111年10月14日

(高雄市湖內區)

採樣單位：御安淨水企業有限公司

報告日期：111年10月20日

採樣方法：---

報告編號：C1113793-6

採樣行程代碼： ---

[illegible]

樣品檢驗報告

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司	委託編號：YZ1111C3793
委託者地址：桃園市平鎮區中豐路南勢二段 127 號	樣品基質：飲用水
受檢單位：錄興國際股份有限公司	檢測目的：定檢
行業別：自述業別	採樣時間：111年10月13日15時35分
採樣地點：高雄長春一館 B2/2F 飲水機 (高雄市湖內區)	收樣時間：111年10月14日
採樣單位：御安淨水企業有限公司	報告日期：111年10月20日
採樣方法：---	報告編號：C1113793-8
採樣行程代碼：---	

樣品報告編號		C1111014E				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
總菌落數	CFU/mL	<5	111年10月14日 12時00分	TGE Agar	1倍/0，0	NIEA E203.56B	100	
以下空白								

樣品檢驗報告

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段127號
 受檢單位：錄興國際股份有限公司
 行業別：自述業別
 採樣地點：高雄長春一館B4/4F 飲水機
 (高雄市湖內區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1111C3793
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：111年10月13日15時45分
 收樣時間：111年10月14日
 報告日期：111年10月20日
 報告編號：C1113793-10

樣品報告編號		C1111014G				檢驗 方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
總菌落數	CFU/mL	<5	111年10月14日 12時00分	TGE Agar	1倍/0，0	NIEA E203.56B	100	
以下空白								

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司	委託編號：YZ1111C3793
委託者地址：桃園市平鎮區中豐路南勢二段 127 號	樣品基質：飲用水
受檢單位：錄興國際股份有限公司	檢測目的：定檢
行業別：自述業別	採樣時間：111年10月13日15時50分
採樣地點：高雄長春一館 B5/5F 飲水機 (高雄市湖內區)	收樣時間：111年10月14日
採樣單位：御安淨水企業有限公司	報告日期：111年10月20日
採樣方法：---	報告編號：C1113793-11
採樣行程代碼：---	

樣品報告編號		C1111014H				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
總菌落數	CFU/mL	<5	111年10月14日 12時00分	TGE Agar	1倍/0，0	NIEA E203.56B	100	
以下空白								

元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段 127 號
 受檢單位：錄興國際股份有限公司
 行業別：自述業別
 採樣地點：高雄長春一館 B6/6F 飲水機
 (高雄市湖內區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1111C3793
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：111年10月13日15時55分
 收樣時間：111年10月14日
 報告日期：111年10月20日
 報告編號：C1113793-12

樣品報告編號		C1111014I				檢驗 方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
總菌落數	CFU/mL	<5	111年10月14日 12時00分	TGE Agar	1倍/0, 0	NIEA E203.56B	100	
以下空白								

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden-Brother International Co., Ltd.

IndustrialType: ---

Sampling Site: Kaohsiung Changchun 1st Building B2/2F Water Dispenser

Client Number: YZ1111C3793

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 10/13/2022 15:35

Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 10/20/2022

Report Number: C1113793-2

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden –Brother International Co., Ltd.
IndustrialType: ---
Sampling Site: Kaohsiung Changchun 1st BuildingB4/ 4F Water Dispenser

Client Number: YZ1111C3793
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 10/13/2022 15:45
Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 10/20/2022
Report Number: C1113793-4

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden-Brother International Co., Ltd.

IndustrialType: ---

Sampling Site: Kaohsiung Changchun 1st BuildingB5/ 5F Water Dispenser

Client Number: YZ1111C3793

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 10/13/2022 15:50

Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 10/20/2022

Report Number: C1113793-5

[illegible]

Environmental Technology Research Center

YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden –Brother International Co., Ltd.

IndustrialType: ---

Sampling Site: Kaohsiung Changchun 1st Building B1/1F Water Dispenser

Client Number: YZ1111C3793

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 10/13/2022 15:30

Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 10/20/2022

Report Number: C1113793-7

Sample Report Number		C1111014D				Analytical Method	Drinking water standard of EPA	Remarks
Sample Name(Number)		Drinking fountain						
Analyzed Item	Unit	Analytical Value	Start Time of Incubating	Medium	Original Data			
Total Bacterial Count	CFU/mL	<5	10/14/2022 12:00	TGE Agar	1/0 , 0	NIEA E203.56B	100	
The END								
				</				

PASS

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden -Brother International Co., Ltd.
IndustrialType: ---
Sampling Site: Kaohsiung Changchun 1st Building B2/2F Water Dispenser

Client Number: YZ1111C3793
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 10/13/2022 15:35
Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 10/20/2022
Report Number: C1113793-8

Sample Report Number		C1111014E				Analytical Method	Drinking water standard of EPA	Remarks
Sample Name(Number)		Drinking fountain						
Analyzed Item	Unit	Analytical Value	Start Time of Incubating	Medium	Original Data			
Total Bacterial Count	CFU/mL	<5	10/14/2022 12:00	TGE Agar	1/0 , 0	NIEA E203.56B	100	
The END								

PASS

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden -Brother International Co., Ltd.
IndustrialType: ---
Sampling Site: Kaohsiung Changchun 1st BuildingB3/ 3F Water Dispenser

Client Number: YZ1111C3793
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 10/13/2022 15:40
Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 10/20/2022
Report Number: C1113793-9

Sample Report Number		C1111014F				Analytical Method	Drinking water standard of EPA	Remarks
Sample Name(Number)		Drinking fountain						
Analyzed Item	Unit	Analytical Value	Start Time of Incubating	Medium	Original Data			
Total Bacterial Count	CFU/mL	<5	10/14/2022 12:00	TGE Agar	1/0 , 0	NIEA E203.56B	100	
The END								
				</				

PASS

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden –Brother International Co., Ltd.
IndustrialType: ---
Sampling Site: Kaohsiung Changchun 1st Building B4/ 4F Water Dispenser

Client Number: YZ1111C3793
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 10/13/2022 15:45
Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---
Report Date: 10/20/2022
Report Number: C1113793-10

Sample Report Number		C1111014G				Analytical Method	Drinking water standard of EPA	Remarks
Sample Name(Number)		Drinking fountain						
Analyzed Item	Unit	Analytical Value	Start Time of Incubating	Medium	Original Data			
Total Bacterial Count	CFU/mL	<5	10/14/2022 12:00	TGE Agar	1/0 , 0	NIEA E203.56B	100	
The END								

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden –Brother International Co., Ltd.
IndustrialType: ---
Sampling Site: Kaohsiung Changchun 1st Building B5/5F Water Dispenser

Client Number: YZ1111C3793
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 10/13/2022 15:50
Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 10/20/2022
Report Number: C1113793-11

Sample Report Number		C1111014H				Analytical Method	Drinking water standard of EPA	Remarks
Sample Name(Number)		Drinking fountain						
Analyzed Item	Unit	Analytical Value	Start Time of Incubating	Medium	Original Data			
Total Bacterial Count	CFU/mL	<5	10/14/2022 12:00	TGE Agar	1/0 , 0	NIEA E203.56B	100	
The END								

PASS

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)
Plant: Golden –Brother International Co., Ltd.
IndustrialType: ---
Sampling Site: Kaohsiung Changchun 1st Building B6/6F Water Dispenser

Client Number: YZ1111C3793
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 10/13/2022 15:55
Sample Received: 10/14/2022

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---
Report Date: 10/20/2022
Report Number: C1113793-12

Sample Report Number		C1111014I				Analytical Method	Drinking water standard of EPA	Remarks
Sample Name(Number)		Drinking fountain						
Analyzed Item	Unit	Analytical Value	Start Time of Incubating	Medium	Original Data			
Total Bacterial Count	CFU/mL	<5	10/14/2022 12:00	TGE Agar	1/0 , 0	NIEA E203.56B	100	
The END								

P7/7