



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
委託者地址：桃園市平鎮區中豐路南勢二段127號
受檢單位：家興人力資源顧問股份有限公司
行業別：自述業別
採樣地點：龜山文華館 C02/2F 飲水機
(桃園市龜山區)
採樣單位：御安淨水企業有限公司
採樣方法：---
採樣行程代碼：---

委託編號：YZ1121C0834
樣品基質：飲用水
檢測目的：定檢
採樣時間：112年03月02日15時00分
收樣時間：112年03月03日
報告日期：112年03月06日
報告編號：C1120834-1

樣品報告編號		C1120303R				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0 , 0	NIEA E230.55B	6	
以下空白								
		PASS						



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
委託者地址：桃園市平鎮區中豐路南勢二段 127 號
受檢單位：家興人力資源顧問股份有限公司
行業別：自述業別
採樣地點：龜山文華館 C09/2F 飲水機
(桃園市龜山區)
採樣單位：御安淨水企業有限公司
採樣方法：---
採樣行程代碼：---

委託編號：YZ1121C0834
樣品基質：飲用水
檢測目的：定檢
採樣時間：112年03月02日15時05分
收樣時間：112年03月03日
報告日期：112年03月06日
報告編號：C1120834-2

樣品報告編號		C1120303S				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0, 0	NIEA E230.55B	6	
以下空白								
		PASS						



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段 127 號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C10/2F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C0834
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年03月02日15時10分
 收樣時間：112年03月03日
 報告日期：112年03月06日
 報告編號：C1120834-3

樣品報告編號		C1120303T				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0 , 0	NIEA E230.55B	6	
以下空白								
		PASS						



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段 127 號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C11/2F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C0834
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年03月02日15時15分
 收樣時間：112年03月03日
 報告日期：112年03月06日
 報告編號：C1120834-4

樣品報告編號		C1120303U				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0, 0	NIEA E230.55B	6	
以下空白								
								



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段 127 號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C12/2F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C0834
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年03月02日15時20分
 收樣時間：112年03月03日
 報告日期：112年03月06日
 報告編號：C1120834-5

樣品報告編號		C1120303V				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0, 0	NIEA E230.55B	6	
以下空白								



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段127號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C13/2F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C0834
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年03月02日15時25分
 收樣時間：112年03月03日
 報告日期：112年03月06日
 報告編號：C1120834-6

樣品報告編號		C1120303W				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0, 0	NIEA E230.55B	6	
以下空白								
								



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段127號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C14/1F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C0834
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年03月02日15時30分
 收樣時間：112年03月03日
 報告日期：112年03月06日
 報告編號：C1120834-7

樣品報告編號		C1120303X				檢驗方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0 , 0	NIEA E230.55B	6	
以下空白								



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段 127 號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：龜山文華館 C15/1F 飲水機
 (桃園市龜山區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C0834
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年03月02日15時35分
 收樣時間：112年03月03日
 報告日期：112年03月06日
 報告編號：C1120834-8

樣品報告編號		C1120303Y				檢驗 方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年03月03日 12時00分	LES Endo Agar	1 倍/0，0	NIEA E230.55B	6	
以下空白								

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C09/2F drinking fountain

Client Number: YZ1121C0834

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 03/02/2023 15:05

Sample Received: 03/03/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 03/06/2023

Report Number: C1120834-2

[illegible]

Environmental Technology Research Center

YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C10/2F drinking fountain

Client Number: YZ1121C0834

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 03/02/2023 15:10

Sample Received: 03/03/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 03/06/2023

Report Number: C1120834-3

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C1 1/2F drinking fountain

Client Number: YZ1121C0834

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 03/02/2023 15:15

Sample Received: 03/03/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 03/06/2023

Report Number: C1120834-4

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C12/2F drinking fountain

Client Number: YZ1121C0834

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 03/02/2023 15:20

Sample Received: 03/03/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 03/06/2023

Report Number: C1120834-5

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C13/2F drinking fountain

Client Number: YZ1121C0834

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 03/02/2023 15:25

Sample Received: 03/03/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 03/06/2023

Report Number: C1120834-6

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY

Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Lucky dorm C15/1F drinking fountain

Client Number: YZ1121C0834

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 03/02/2023 15:35

Sample Received: 03/03/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 03/06/2023

Report Number: C1120834-8

[illegible]