



元智大學環科中心檢測實驗室

樣品檢驗報告

委託單位：御安淨水企業有限公司
 委託者地址：桃園市平鎮區中豐路南勢二段127號
 受檢單位：家興人力資源顧問股份有限公司
 行業別：自述業別
 採樣地點：蘆竹五福一館1F 飲水機
 (桃園市蘆竹區)
 採樣單位：御安淨水企業有限公司
 採樣方法：---
 採樣行程代碼：---

委託編號：YZ1121C3316
 樣品基質：飲用水
 檢測目的：定檢
 採樣時間：112年08月15日16時00分
 收樣時間：112年08月16日
 報告日期：112年08月23日
 報告編號：C1123316-1

樣品報告編號		C1120816U				檢驗 方法	環保署 飲用水 標準值	備註欄
原樣名稱或編號		飲用水						
檢測項目	單位	檢測值	開始培養時間	培養基名稱	原始數據			
大腸桿菌群	CFU/100 mL	<1	112年08月16日 14時00分	LES Endo Agar	1 倍/0 , 0	NIEA E230.55B	6	
以下空白								
		PASS						

元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1121C3316

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：112年08月15日16時05分

採樣地點：蘆竹五福一館 2F 飲水機

收樣時間：112年08月16日

(桃園市蘆竹區)

採樣單位：御安淨水企業有限公司

報告日期：112年08月23日

採樣方法：---

報告編號：C1123316-2

採樣行程代碼：---

[illegible]



樣品檢驗報告

採樣行程代碼：---

[illegible]

元智大學環科中心檢測實驗室

樣品檢驗報告

委 託 單 位：御安淨水企業有限公司

委託編號：YZ1121C3316

委託者地址：桃園市平鎮區中豐路南勢二段127號

樣品基質：飲用水

受 檢 單 位：家興人力資源顧問股份有限公司

檢測目的：定檢

行 業 別 : 自述業別

採樣時間：112年08月15日16時15分

採樣地點：蘆竹五福一館 4F 飲水機

收樣時間：112年08月16日

(桃園市蘆竹區)

採樣單位：御安淨水企業有限公司

報告日期：112年08月23日

採樣方法：---

報告編號：C1123316-4

採樣行程代碼：---

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Plant: Golden Li H.R Consultant Co., Ltd

IndustrialType: ---

Sampling Site: Luzhu Wufu Building 2F Water Dispenser

Client Number: YZ1121C3316

Sample Base: Drinking Water

Test purpose: Regular inspection

Sampling Date: 08/15/2023 16:05

Sample Received: 08/16/2023

Sampling Organization: Yuann International Technology Co., Ltd

Sampling Method: ---

Sampling Code: ---

Report Date: 08/23/2023

Report Number: C1123316-2

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd
Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan
County, Taiwan (R.O.C.)
Plant: Golden Li H.R Consultant Co., Ltd
IndustrialType: ---
Sampling Site: Luzhu Wufu Building 3F Water Dispenser

Client Number: YZ1121C3316
Sample Base: Drinking Water
Test purpose: Regular inspection
Sampling Date: 08/15/2023 16:10
Sample Received: 08/16/2023

Sampling Organization: Yuann International Technology Co., Ltd
Sampling Method: ---
Sampling Code: ---

Report Date: 08/23/2023
Report Number: C1123316-3

[illegible]

Environmental Technology Research Center
YUAN ZE UNIVERSITY
Analysis Report

Client: Yuann International Technology Co., Ltd

Client Number: YZ1121C3316

Address: No.127, Nanshi Sec. 2, Zhongfeng Rd., Pingzhen City, Taoyuan County, Taiwan (R.O.C.)

Sample Base: Drinking Water

Plant: Golden Li H.R Consultant Co., Ltd

Test purpose: Regular inspection

IndustrialType: ---

Sampling Date: 08/15/2023 16:15

Sampling Site: Luzhu Wufu Building 4F Water Dispenser

Sample Received: 08/16/2023

Sampling Organization: Yuann International Technology Co., Ltd

Report Date: 08/23/2023

Sampling Method: ---

Report Number: C1123316-4

Sampling Code: ---

[illegible]